


HDPE tvarovky: prechod ocel' / PE 100 s predĺžením



- Zváranie na tupo nedoporučujeme
- Neskracujte oceľovú časť



d _n	D	rozmery			hmostnosti
					PE 100
		h	h ₁	Z	SDR 11
					PN 16 - S5
25	3/4"	300	100	495	590
32	1"	300	105	499	950
40	1" 1/4	300	106	508	1200
50	1" 1/2	300	120	516	1450
63	2"	300	135	545	1900